

## Attachment 3 Photographs of typical civil works



**Figure 1: Gates on a channel before automation**



**Figure 2: Gates on a channel after automation**

Attachment 3 Photographs of typical civil works



Figure 3: Before and after automation of a large channel regulator.

### Attachment 3 Photographs of typical civil works



**Figure 4: A channel in the Central Goulburn system before remediation works (undertaken as part of the CG1-4 Project).**



**Figure 5: A channel in the Central Goulburn system after the channel was lined with HDPE plastic.**

### Attachment 3 Photographs of typical civil works



Figure 6: A Large Dethridge Wheel (LMO).



Figure 7: An installed MagFlow meter